

C.A.TECHNOLOGIES AIR ASSIST AIRLESS TIP LIST

C.A.T. Part #	DESCRIPTION	KREMLIN Part #	Spray Angle (degrees)	Pattern Width (inches)	Orifice Size
36-207	AA TIP ASSY. - 207	03-03	20	4	0.007
36-407	AA TIP ASSY. - 407	03-07	50	8	0.007
36-309	AA TIP ASSY. - 309	04-05	30	6	0.009
36-409	AA TIP ASSY. - 409	04-07	40	8	0.009
36-509	AA TIP ASSY. - 509	04-11	50	10	0.009
36-609	AA TIP ASSY. - 709	04-13	70	14	0.009
36-211	AA TIP ASSY. - 211	06-03	20	4	0.011
36-311	AA TIP ASSY. - 311	06-05	30	6	0.011
36-411	AA TIP ASSY. - 411	06-07	40	8	0.011
36-511	AA TIP ASSY. - 511	06-11	50	10	0.011
36-611	AA TIP ASSY. - 611	06-13	60	12	0.011
36-711	AA TIP ASSY. - 711	06-15	70	14	0.011
36-213	AA TIP ASSY. - 213	09-03	20	4	0.013
36-313	AA TIP ASSY. - 313	09-05	30	6	0.013
36-413	AA TIP ASSY. - 413	09-09	40	8	0.013
36-513	AA TIP ASSY. - 513	09-11	50	10	0.013
36-613	AA TIP ASSY. - 613	09-13	60	12	0.013
36-713	AA TIP ASSY. - 713	09-15	70	14	0.013
36-315	AA TIP ASSY. - 315	12-05	30	6	0.015
36-415	AA TIP ASSY. - 415	12-07	40	8	0.015
36-515	AA TIP ASSY. - 515	12-11	50	10	0.015
36-615	AA TIP ASSY. - 615	12-13	60	12	0.015
36-715	AA TIP ASSY. - 715	12-15	70	14	0.015
36-815	AA TIP ASSY. - 815	12-17	80	16	0.015
36-317	AA TIP ASSY. - 317	(18 or 14)-05	30	6	0.017
36-417	AA TIP ASSY. - 417	(18 or 14)-09	40	8	0.017
36-517	AA TIP ASSY. - 517	(18 or 14)-11	50	10	0.017
36-617	AA TIP ASSY. - 617	(18 or 14)-13	60	12	0.017
36-717	AA TIP ASSY. - 717	(18 or 14)-15	67	14	0.017
36-419	AA TIP ASSY. - 419		40	8	0.019
36-619	AA TIP ASSY. - 619		60	12	0.019
36-621	AA TIP ASSY. - 621	20-136	60	12	0.021
36-721	AA TIP ASSY. - 721	20-136	70	14	0.021
36-425	AA TIP ASSY. - 425	20-156	40	8	0.025
36-625	AA TIP ASSY. - 625		60	12	0.025